

Utility Cut Repair Inspections City of Toronto Case Study

Lori Schaus, MAsc., P.Eng. Senior Pavement Engineer (ARA)

Claude Laflamme, BSc. Director of Research & Development (Rival Solutions, Inc.)

CERIU

24th INFRA Conference

November 20, 2018



Contents

- Background
- Project Purpose and Solution
- Key Issues
- Study Methodology
- Challenges
- Lessons Learned



Background

- What is a Utility Cut?
 - Any excavation or cutting of roadway or roadside within the city right of way for the purpose of utility work.




Temporary vs Permanent Repair?

- Temporary repair completed by the Utility.
- Permanent repair carried out by the City.



Temporary



Permanent

Background

- City of Toronto (CoT) issues > 50,000 permits for utility cuts annually.
- The utility completes a “temporary” restoration and monitors for up to 18 months.
- Permanent repairs are then carried out by CoT.
- CoT recovers: Repair costs, overhead expenses, and a pavement degradation fee from the Utility.

Background

- CoT staffing required to keep up with the backlog of permit inspections currently exceeds capacity.
- Over 18,000 permits (2008-2014) required condition verification and inspection.
- Permit restoration backlogs can extend back for a number of years.
- Verification and restoration backlog completion is not unique to the City of Toronto and quite common for many major metropolitan cities.

Project Purpose

- Inspect cuts, determine if utility work was completed:
 - **Yes?** → Indicate “No Work Required.”
 - **No?** → Mark repair area and obtain repair quantities.
- Update City’s database with gathered information.
- Develop a 2-year work program to eliminate the backlog.

Key Issues

- **Volume of Data:** > 18,000 permits.
- **Project Schedule:** Aggressive Schedule (6 months).
- **Staff Availability:** Several Field Inspectors required.
- **Repeatability:** Each inspection may require several tasks.
- **Communication:** Real-time communication between office and field staff was required to identify issues.
- **Productivity:** Work progress needed to be monitored daily.
- **Quality:** Quality assurance was of utmost importance.

Solution

- Semi-automation of inspection and reporting process.
- Tablet cloud-based technology platform using Rival Solution's RUBIX system.

The screenshot shows a mobile application interface for data entry. At the top, it displays the time (11:35 AM), battery level (27%), and location coordinates (-79.59058, 43.66266, ±74.3m, D:41.6 m, #:1). The form is titled "Parent Form UC-Roads-prod". It includes fields for "Segment ID" (0), "WxL: 3.2 x 5 = 16 m²", and "Type" (Longitudinal). Other fields include "Dist_CoCJ" (Within 1 meter of Curb), "Dist_2ndCut" (Single Cut), "Pavement..." (Fair), and "Grind_and..." (Yes, No, CND). There is a "Comments" field and a list of "Items" with columns for item ID, quantity, and unit. The interface is dark-themed with orange buttons and text.

RUBIX DATABASE

RACS Inspections Data

Location Information (GPS,
Ward, Street Segment)



RUBIX

- Flexible cloud-based technology platform.
- Used to store condition information and quantity measurements.
- Uses basic rule-based decision methods.
- Integration of mobile mapping, cloud computing, and web dashboard reporting.
- Used to determine repair costs.

rInspector

- Mobile tablet condition rating application:
 - Configured for CoT repair rules to collect and map cut repair attributes.
 - Enabled effective and timely data collection and delivery.
- Provided a GPS location and digital records of all findings for each inspection.




Exit ARA Permit Master - Prod_20180531 Edit +

< -79.59069, 43.66274, ±65.0m, D:0.0 m, #:1

Zoom to CL

Selection

2018-05-31, 11:32:27 AM EDT (143473547)



12:29 PM

37%

-79.62990, 43.51005, ±41614.0m, D:0.0 m, #:1



ARA Permit Master - Prod

55076315



5401 EGLINTON AVE W

D:0.0 m²



EmployeeID

EmployeeID

Quick_Obs

<Please Select>

2nd_Permit

<Please Select>

2nd_Type

<Please Select>

Comments

Comments

Sub Forms

Other

Roads

SW



UC-Other-prod

55076315

2018-05-09 13:20:09



UC-Other-prod

55076315

2018-05-08 15:39:33



UC-Roads-prod

55076315

2018-05-08 15:09:23



UC-Sidewalk-prod

55076315

2018-05-08 12:47:30



UC-Other-prod

55076315

2018-05-08 12:47:03



iLog

<Please Select>



Images



Legal



Apple

Google

OSM


MB Streets

MB Sats

Offline

rDash

- Web-based dashboard that summarized and presented inspection data collected from the field.
 - Production reporting
 - Quality assurance



Study Methodology

1. Permit database review and geo-referencing
2. RUBIX configuration
3. Inspector training
4. Inspections and dynamic quality assurance
5. Database update and reporting

Permit Review and Geo-Referencing

- Permit Database Review was completed of electronic database information for completeness.
- Permit Geo-Referencing.
 - All permits required geo-referencing in order to be located in the field.
 - Addressing system used to obtain locations for approximately 75% of permits.
 - 5,000 permits had to be manually screened to obtain geo-reference.
 - All permits referenced and located in the field using rInspector.

RUBIX Configuration

- City rules for utility cut repairs were used to configure RUBIX and rInspector.
- Prototype testing and validation was completed by senior team members.
- Field testing ensured the system was capable of geo-referencing permits and collecting the information in a simple and efficient manner.

Inspector Training

- Basic field data collection (traffic control, health and safety).
- rInspector tablet data collection.
- Specific CoT rules for utility cut inspections and repairs.
- In-class and in-field training.

Inspection Types

- **Regular** – Field inspectors completed inspection.
- **Send to Supervisor** – Supervisors completed inspections or provided detailed instructions on how to complete inspection.
- **Traffic Control** – Inspections requiring lane closures to complete inspections.

Inspection Outcomes


- **No work required** – No additional repair required.
- **Work required** – Inspection completed and cut was marked out for permanent repair and attribute data collected.
- **Send to CoT** – Inspection could not be completed or utility cut could not be located and was sent to City for assistance.

Data Collected

- Photographs
- Repair cut dimensions/quantities:
 - Road cuts
 - Sidewalks
 - Curbs
 - Driveways/Aprons
 - Boulevards
 - Adjustments (catchbasins, handwells, utility covers, valves, etc.)
 - Paint markings
 - Tactile walking surface
- All attributes were geo-referenced

Production

Number of Permit Sites Visited (18,759 Sites)



Quality Assurance (QA)

- RUBIX software validation reports generated:
 - 100% of all permits. Checked for human input errors/missing information.
- Supervisor checks completed to validate correct cut, location, mark out requirements, etc.
- Desktop QA checks included Google Streetview reviews.
- Field QA checks included random supervisor re-inspection.

Quality Assurance (QA)



- All reviewed were either “Accepted” or “Rejected”
- All “Rejected” permits were sent back to the inspector for corrective action.
 - These permits remained in the QA cycle until the auditor was satisfied that corrective measures were taken.
 - Corrected permits were updated to “Accepted”.

Quality Achievements

- 100% of permits were field inspected.
- 100% of permit inspections were software checked.
- 30% of permits were reviewed by a quality auditor
 - Combination of desk and/or field audits.
 - The majority of 'failed' audits were a result of:
 - Interpretation of City repair rules.
 - Interpretation of temporary vs. permanent repair.
 - Identification of the correct utility cut.
 - Photograph protocol.

Quality Assurance (QA)

- Audit Tracking
 - Goal – 15% of permits
 - Achieved – 29% of permits



Database Update and Reporting

- RUBIX performed quantity and costs computations.
 - Manual validation was completed.
- Pavement material type and functional class data incorporated from City's pavement management system.
- Cost included:
 - Adjustments for functional class and district.
 - Overhead charges.
 - Pavement degradation fee.
- Database updated and a 2 year work plan was developed.

Challenges

- Permit Location
 - Geo-referencing was required. Automated addressing provided approximately 75% of permits with GPS coordinates.
- Permit Information – variable information provided.
 - Some Utility companies provide more information than others on permits.
- Permit Information Accuracy
 - Accuracy of permit information versus actual field conditions varied significantly.

Challenges

- Urban Development Areas
 - Large construction projects.
 - New urban developments.

- Weather Conditions
 - In-field training in winter months.
 - Winter weather conditions.
 - Wet conditions not conducive to marking paint.
 - Rain/Fog – Traffic control inspections delayed.

Lessons Learned

- Inspection rate is dependent on:
 - Geo-referencing
 - Permit information accuracy
 - Weather
- Clear and concise business rules are required prior to implementation.
- Utility Cut Management Integration
 - Pavement/Asset Management System
 - Quality Management



THANK YOU!