BRIDGING THE GAP

Connecting to the Future of Asset Management

CNAM 2018 Conference May 14-17 Windsor, Ontario

Bridging The Gap On Risk and Level of Service

Luigi Congi, City of Windsor Ronnie Flannery-Guy, Aqua Data Inc. May 15th 2018



Extreme Weather Events Supported Ongoing Sewer System Assessments

- September 29, 2016 the City of Windsor experienced an extreme rainstorm that produced 230mm in the hardest hit areas.
- Mayor Drew Wilkins declared a state of emergency and the Municipal Affairs Minister Bill Mauro activated the Disaster Assistance for Ontarians Program for impacted residence
- City Council agreed to move forward future allocated funds to expedite the completion of the Sanitary and Storm Sewer Master Plan
- > August 28, 2017 the City of Windsor once again experienced record rainfall of 80 to 150 mm. Shortly after Mayor Drew Wilkins outlined an 8-point Plan including:

"a camera project mapping out the city's sewer systems, identifying problems and finding solutions. Without this plan, the city can't move forward with the big underground projects



needed to ultimately solve the problem"





As a Result A Three Stage Approach Taken To Developing Solution

Pilot Program

Review data sets and determine relevancy Identify internal system integration and adaptation Explore impacted processes Identify key stakeholders and end-user

Sole Source

Refine data set and determine use Evaluate system readiness and adaptation Isolate and remove redundancies Analyze existing processes and identify improvements

City – Wide Project

Expand and appropriate system integration Introduce new processes and procedures Improve quality and maintain efficiency





Solution Provided an Integrated Approach in Providing Data to Multiple End Users







Variance reports – Correction forms







Major defects – weekly list





Progress follow up – updated daily





BRIDGING THE GAP

9

Progress follow up – updated daily



+

â

믕

80 25

- Last Day of Inspection
- Inspected
- Not Inspected

Section

- Last Day of Inspection
- Partially Inspected
- Inspected
- Not Inspected
- Excluded from Task Order





Recommendations by area - list





Special Cleaning example

aquaGEO 313 - Citrix XenApp Plugins for Hosted Apps

- 0 ×





Progress follow up – updated daily

| pipe segments with pic | ctures | | | | | NDSOR | Con | nplete PACE |) Hea |
|---|---|---------------|---------------------------------|------------------------|---|-----------------|--------------------------|-------------------------|----------|
| oal Informations | | Pipe Number: | 8\$1621_8\$16 | 89 | | ONTARIO, CANADA | | | nea |
| 1. Inspector Arran Stewart | 2. Certificate Number U-0118-07009625 | | 3. Verifie Francine B | d by Bignell | 4. Certificate # (verify by) U-310-C1084 | | | | |
| 5. Owner | 6. Client Windsor (City of) | | 7. P.O. Number 43-17 | | 8. Work Order Sth_Windsor_Sth | | | | |
| 9. Media | | | 10. Proje | ct | | | | | |
| 11. Date 2018-02-27 | | Measures | Upstream MH 8S1621 | 43. Rim to | Invert (Upstream) | 44. Rim to | Grade (Upstream) | 45. Grade to Invert (U | pstream) |
| 15. Pre-Cleaned N - No Pre-Cleaning | 16. (| | 46. Northing | (Upstream) | 47. Eastin | g (Upstream) | 48. Elevation (Upstream) | | |
| 19. Direction of Survey <i>D</i> - Downstream | 21. In: CI - Cor | 49. D | ownstream MH 8S1689 | 50. Rim to In | ivert (Downstream) | 51. Rim to G | rade (Downstream) | 52. Grade to Invert (Do | wnstream |
| | | | 53. Northing (| Downstream) | 54. Easting | (Downstream) | 55. Eleva | tion (Downstream) | |
| ation | | | 56, MH Coord | inate System | 57. MH Ve | artical Datum | 58. | GPS Accuracy | |
| 24. Drainage Area | | | N/A | | | | | | |
| 26.5 | street | Other Informa | ations | | | | | | |
| WEST GRAND BLVD | | | | | 59. Additiona | al Informations | | | |
| | | Video Filena | me: Sth_Win | idsor_Sth_8S1621 | 8\$1689_8\$1621_ | _2018-02-27-17 | 7-00-16.mp4 | | |
| • | | | | | | | | | |
| 30. Sewer Type SS - Sanitary Sewage Pipe | 31. He | | | | | | | | |
| 34. Material | 35. | Struct | tural Evaluation | Operatio | onal Evaluation | Globa | I Evaluation | Other Evaluation | ins |
| AC - Asbestos Cement | | Ouick | Pating 4131 | Ouick Ra | ating: 5142 | Global R | ating: 24 | Structural Grade: | 4 |
| | | Quint i | auns. TIOT | | | | | | |





Pipe register index





Improved Precision and Accuracy Achieved with a System Wide Assessment

- Complete inventory of system (manholes, catch basins, chambers, and sewer pipe conditions)
- Clearly define sewer operational and structural condition ratings since flushing has the potential of removing evidence of operational conditions
- Provides guidance into where further CCTV inspection is needed
- Basis for creating a more efficient flushing program (flushing lines that need it and reducing damage from flushing activities)
- Reduced operational cost in obtaining a system-wide assessment (no flushing needed prior to inspection)
- Less time and cost involved compared to traditional CCTV inspection





Established Framework Maximizes Service Levels and Minimizes Risk

- Comprehensive system-wide assessment of operational and structural condition of an asset
- Ability to continuously monitor sewer degradation without causing further flushing damage
- > Operational ratings form the baseline for periodic monitoring of flow conditions over time
- Inspection results assist in developing an effective and efficient sewer flushing program resulting in cost savings and longevity to sewer lines
- Historical condition ratings captured from the inspection program are used to refine CCTV inspection programs
- Ability to identify relining needs prior to deterioration, prolonging asset life in a cost effective manner



Questions





18